## IN THE UNITED STATES PATENT & TRADEMARK OFFICE

IN RE APPLICATION OF: U.S. Patent No. 7,245,922

USPTO CONFIRMATION CODE: 5091

APPLICATION NO.: 09/899,242

FILED: July 6, 2001

EXAMINER: Edward F. Urban

**GROUP ART UNIT: 2618** 

FOR: METHOD AND APPARATUS FOR CONTROLLING QUALITY OF SERVICE FOR MULTIPLE SERVICES THROUGH POWER SETTING

## 37 CFR 1 322 & 37 CFR 1 323 REQUEST FOR CERTIFICATE OF CORRECTION FOR USPTO AND/OR APPLICANT MISTAKE

## HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

SIR:

The following is a request for a certificate of correction in Serial Number 09/899,242, now Patent Number 7,245,922.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

The errors were the fault of both the applicant and USPTO and, accordingly, please charge <u>\$100.00</u> to our Deposit Account No. 50-1379. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The exact locations where the errors appear in the patent and patent application are as follows:

In Figure 4, Sheet 2 of 3, under "POWER OFFSET", Line 5, delete "4-9+3=0dB" and insert - - 4-9+3=2dB - -, therefor.

(ORIGINALLY FILED SPECIFICATION, IN THE DRAWINGS DATED JULY 6, 2001, SHEET 2 OF 3, UNDER "POWER OFFSET", LINE 5)

In Column 8, Line 36, in Claim 1, after "groups;" insert - - and, - -. (AMENDMENTS TO THE CLAIMS DATED NOVEMBER 4, 2004, PAGE 2 OF 14, CLAIM 1, LINE 13)

In Column 11, Line 35, in Claim 43, delete "far" and insert - - for - -, therefor. (AMENDMENTS TO THE CLAIMS DATED NOVEMBER 4, 2004, PAGE 10 OF 14, CLAIM 59, LINE 2)

The requested corrections are attached on Form PTO 1050.

Respectfully Submitted

, 2007 /SIDNEY L. WEATHERFORD,Reg#45602/

DATE Sidney L. Weatherford

Registration No. 45602

Attorney of Record